PLANS S-241(1)

DEED DESCRIPTION PARCEL 00-0027-8915

AS FOUND ON A WARRANTY DEED IN THE DUCHESNE COUNTY RECORDER'S OFFICE

LOT 1, BLACKPOWDER RANCHETTES SUBDIVISION, ACCORDING TO THE OFFICIAL PLAT THEREOF AS FOUND IN THE OFFICE OF THE RECORDER, DUCHESNE COUNTY, UTAH.

TOGETHER WITH ALL IMPROVEMENTS AND APPURTENANCES THEREUNTO BELONGING. SUBJECT TO ALL EXISTING EASEMENTS AND RIGHTS OF WAY. EXCEPTING THEREFROM ALL OIL, GAS, AND MINERAL RIGHTS

NORTH QUARTER CORNER

SECTION 5, T. 2 S., R. 1 W. FOUND DUCHESNE CO.

ALUM, CAP 1994

FOUND 4" Ø METAL PIPE

Berta Melgoza Lot #6 00-0027-8964

FOUND 4" Ø METAL PIPE

POST AT CORNER -SEE NOTE #3

N88°55'51"E 166.37'

AT CORNER -SEE NOTE #3

1. THE PURPOSE OF THIS SURVEY WAS TO LOCATE AND STAKE CERTAIN CORNERS OF THE HEREON DESCRIBED PARCEL OF LAND.

2. BASIS OF BEARING USED WAS N88°53'04"E BETWEEN THE NORTHWEST CORNER AND THE NORTH QUARTER CORNER OF SECTION 5, T. 2 S., R. 1 W., U.S.B. & M.

3. DURING THE COURSE OF THIS SURVEY METAL POSTS OF VARIOUS DIAMETERS WERE LOCATED AT OR NEAR THE ACTUAL CORNER OF THE LOTS WHILE LOOKING FOR THE CORNERS OF THE LOTS RECORDER'S OFFICE IN BOOK A-107 PAGES 417-420. THE METAL POSTS ARE CEMENTED INTO PLACE WITH NO TRACE OF THE REBAR AND ARE THE BEST AVAILABLE EVIDENCE OF THE ORIGINAL LOT CORNERS LOCATIONS.


4. THE NORTHWEST CORNER OF SAID SECTION 5 WAS RE-ESTABLISHED USING THE FOUND REBAR AND CAPS AND THE FOUND NORTH QUARTER CORNER AS SHOWN ON THE RECORD OF SURVEY PLAT FOR FRED GOODRICH PERFORMED BY UINTAH ENGINEERING AND LAND SURVEYING IN JULY OF 2018, ON FILE AS NUMBER 3777 AT THE UINTAH COUNTY SURVEYOR'S OFFICE.

WEST LINE OF LOT #10 APPEAR TO HAVE BEEN ESTABLISHED ALONG THE LOCATED FENCE LINE. DURING THIS SURVEY AT THE NORTHWEST CORNER OF THE ORIGINAL SUBDIVISION, A METAL PIPE POST WAS LOCATED THAT MATCHES THE ORIGINAL PLATS BEARINGS AND DISTANCES. BUT THE EXISTING FENCE CORNER LOCATED APPROXIMATELY 17 FEET TO THE EAST DOESN'T AGREE WITH THE ORIGINAL PLAT. THE RECORD OF SURVEY FOR FRED GOODRICH ESTABLISHED A POINT ON THE ACTUAL RIGHT OF WAY NEAR THE SAID FENCE CORNER. THIS SET CORNER WAS CONFIRMED BY LOOKING AT THE UDOT PLANS FOR THE ROADWAY AND IT SHOWED THE RIGHT OF WAY FOLLOWING THE EXISTING FENCE LINE AND THE JOG OUT TO THE EAST AS SHOWN ON THIS SURVEY AND THE

SURVEYOR'S CERTIFICATE

I, TROY W. GADD, A REGISTERED LAND SURVEYOR AS PRESCRIBED BY THE LAWS OF THE STATE OF UTAH, HOLDING CERTIFICATE #5561169, CERTIFY THAT THE SURVEY SHOWN HEREON WAS MADE UNDER MY

I FURTHER CERTIFY THAT THIS PLAT CORRECTLY SHOWS THE DIMENSIONS OF THE PROPERTY SURVEYED.



PREPARED BY:

Jones & DeMille Engineering, Inc.

CIVIL ENGINEERING - SURVEYING - TESTING - GIS - ENVIRONMENTAL - infrastructure professionals -1.800.748.5275 www.jonesanddemille.com

DRAWN BY: TWG UPDATED: 7/11/2019 PLOTTED: 7/11/2019

h:\jd\proj\1906-446\dwg\1906-446 survey.dwg

Mayra Sanchez Record of Survey

> Duchesne County, Utah Scale: 1" = 100'

County Surveyors File # 4225